0011

From: Karl Houskeeper

CC:

rnetz@emerytelcom.net

To:

Angela Nance; Daron Haddock; Suzanne Steab

Date:

8/4/2009 1:57 PM

Subject:

July 2009 Inspection Reports

Attachments: SPWF July 2009.pdf; SCA July 2009.pdf

Rusty,

Attached is the July 2009 inspection reports for SPWF and SCA.

Thanks,

Karl

Outgines C0070035

Œ



State of Utah

Department of **Natural Resources**

MICHAEL R. STYLER Executive Director

Division of Oil, Gas & Mining

> JOHN R. BAZA Division Director

JON M. HUNTSMAN, JR. Governor

GARY R. HERBERT Lieutenant Governor

Representatives Present During the Inspection:					
Company	Rusty Netz Environmental Coordinator				
OGM	Karl Houskeeper Environmental Scientist III				

Inspection Report

Permit Number:	C0070035		
Inspection Type:	PARTIAL		
Inspection Date:	Thursday, July 16, 2009		
Start Date/Time:	7/16/2009 10:30:00 AM		
End Date/Time:	7/16/2009 2:30:00 PM		
Last Inspection:	Thursday, June 18, 2009		

Inspector: Karl Houskeeper, Environmental Scientist III

Weather: Clear, Temp. 88 Deg. F. InspectionID Report Number: 2067

Accepted by: jhelfric

8/4/2009

Permitee: SUNNYSIDE COGENERATION ASSOCIATES

Operator: SUNNYSIDE COGENERATION ASSOCIATES

Site: SUNNYSIDE REFUSE & SLURRY

Address: ONE POWER PLANT RD, PO BOX 159 SUNNYSIDE UT 84539

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current A	Acreages	Mineral Ownership	Types of Operations		
310.00	Total Permitted	☐ Federal	Underground		
202.00	Total Disturbed	☐ State	☐ Surface		
	Phase I	☐ County	☐ Loadout		
	Phase II	✓ Fee	Processing		
	Phase III	☐ Other	✓ Reprocessing		

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

There are no pending compliance actions. The only permit condition currently in place is that the permittee must submit all water monitoring data in an electronic format to the Division's web site. The permittee is complying with this stipulation.

Inspector's Signature:	Sarl R. Douskuser	Date	Thursday, July 16, 2009

Karl Houskeeper, Environmental Scientist III

Inspector ID Number: 49

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Permit Number: C0070035 Inspection Type: PARTIAL

Inspection Date: Thursday, July 16, 2009

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- Substantiate the elements on this inspection by checking the appropriate performance standard.
 a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
- b. For PARTIAL inspections check only the elements evaluated.
 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
 Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale	\checkmark		\checkmark	
2.	Signs and Markers	✓		V	
3.	Topsoil				
4.a	Hydrologic Balance: Diversions				
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	✓			
4.c	Hydrologic Balance: Other Sediment Control Measures				
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives	V	✓		
6.	Disposal of Excess Spoil, Fills, Benches	V		✓	
7.	Coal Mine Waste, Refuse Piles, Impoundments	V		✓	
8.	Noncoal Waste	V			
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage				
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations				
16.a	Roads: Construction, Maintenance, Surfacing				
16.b	Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

Permit Number: C0070035 Inspection Type: PARTIAL

Inspection Date: Thursday, July 16, 2009

Page 3 of 3

1. Permits, Change, Transfer, Renewal, Sale

There are no pending compliance actions. The only permit condition currently in place is that the permittee must submit all water monitoring data in an electronic format to the Division's web site. The permittee is complying with this stipulation.

2. Signs and Markers

The mine ID sign is located adjacent to the tipple on a light pole. The MSHA Refuse Pile sign was also checked during the inspection and contained the required information.

6. Disposal of Excess Spoil, Fills, Benches

Excess spoil pile is actively receiving material. The pile is raised above the natural ground level and is being constructed according to the approved design in the mining and reclamation permit.

7. Coal Mine Waste, Refuse Piles, Impoundments

The refuse pile appeared stable with no visible hazards.